

PARTS LIST

NO	DESCRIPTION	IMAGE	QTY
P1	TABLE TOP		1
P2	LEGS		2
P3	PLATE		4

HARDWARE LIST

NO	DESCRIPTION	IMAGE	QTY
H1	ALLEN BOLT M6X20		17
H2	MACHINE SCREW M8X20		8
H3	ALLEN KEY		1


TOOLS REQUIRED (NOT INCLUDED)




SCREW DRIVER

NOTE: PO# is located underneath/ inside of each item. Please be prepared to provide this # should any claim be necessary.



CAUTION: Item is heavy assembly should be performed by two people.



3



1



2

ASSEMBLY COMPLETED