

WYNN DESK

Assembly instructions:

PARTS LIST

No.	DESCRIPTION	IMAGE	QTY
P1	TABLE TOP		1
P2	BODY		1
P3	U FRAME		1
P4	LEGS FRAME		1
P5	CONNECTORS		2
P6	LEGS		2


HARDWARE LIST

No.	DESCRIPTION	IMAGE	QTY
H1	BOLT 1/4" x 20		8
H2	BOLT 1/4" x 45		5
H3	BOLT 1/4" x 120		2
H4	SPRING WASHER		15
H5	FLAT WASHER		15
H6	WOOD PLUG		5
H7	ALLEN KEY		1


NOTE: PO# is located underneath/ inside of each item. Please be prepared to provide this # should any claim be necessary.

CAUTION: Item is heavy assembly should be performed by two people.


1



2



3



4

